ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mananagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 6 | Thanisandra |

| Street ID | Street Name | Significant Landmark |
|---|---|---|
| W0006, W0020, W0081, W0079, W1148, W0068, W0077 | NA, 14th Crs, Om Shakthi Lyt 4th Crs, 2nd Main Rd | Hegdenagar Circle |

| Segment No. | Total Length (m) |
|---|---|
| 6/C-W0006/S121910 | 812.22 |

Segment Details

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 141.05 | 77.632806 | 13.073111 | 77.632806 | 13.071836 | 1st Cross | End |
| 2 | 112.16 | 77.633171 | 13.072808 | 77.633160 | 13.071794 | 2nd Cross | End |
| 3 | 191.35 | 77.632436 | 13.071773 | 77.632425 | 13.070044 | 3rd Cross | End |
| 4 | 186.72 | 77.632795 | 13.071763 | 77.632795 | 13.070075 | 1st Cross | End |
| 5 | 180.94 | 77.633155 | 13.071737 | 77.633160 | 13.070101 | 2nd Cross | End |

### Work Details

History of Road / Lane / Circles

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drains in Hedgenagar West 3rd and 4th Cross in Ward No.06 | 20000000 | 2019-20 |

| Year | Type of Work | Other Work Type |
|---|---|---|
| 2020 - 2021 | Others | Drain |

| Tender | Work Details | Job No. / Work Code |
|---|---|---|
| Tender | RCC Drain, Slab and Kerbstone | 006-20-000170 |

| Work Order No. | Work Order Date | Period of Extention |
|---|---|---|
| EE(Project)/Ynk Zone/WO/39/2020-21 | 01/07/2020 | |

| Defect Liability Period From | Defect Liability Period To | Multiple road involved with the same Job No/ Work Code # |
|---|---|---|
| 20/02/2021 | 19/02/2022 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| S D Venkatesh Gowda | | 0.00 |

| Phone No. | E-Mail ID |
|---|---|
| 9741704059 | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Anjaneyalu B R |
| **Date of Inspection** | **Remarks** | |
| 25/05/2021 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Footpath Condition | | This photo seems out of range. |
| Segment End | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Sri.S.P.Ranganath | 25/05/2021 | 24/06/2021 | As proposed |
| SE | Vijay Kumar Haridas | 25/05/2021 | 24/06/2021 | Approved |
| EE | Devendra Naik | 25/05/2021 | 24/06/2021 | Approved |
| AEE | R Naveen Kumar | 25/05/2021 | 24/06/2021 | Approved |
| AE | Anjaneyalu B R | 25/05/2021 | 24/06/2021 | Verified |
| AE | Anjaneyalu B R | 25/05/2021 | 24/06/2021 | |

**Zone:** YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0006, W0020, W0081, W0079,